

ABSTRACT

W powder is produced by: preparing a precursor containing tungsten; producing gas by vaporizing or sublimating the precursor; separating the tungsten component by placing the gas in an
5 inert atmosphere while maintaining pressure below atmospheric pressure; and condensing the tungsten component at pressure below atmospheric pressure.